


Exhibit EN-HLD-5 Viewshed Analysis Map
Scenarios 2 and 3: Decommissioning and Dismantling

June 06, 2014

Visibility analysis performed by Dodson & Flinker, Inc. in ArcMap 10.2, using 10M Digital Elevation Model from the USGS (c. 2010) and forest/building obstructions digitized in ArcMap 10.2 from 0.3 meter resolution ESRI World Imagery (c. 04/09/2011).



- Not Visible
- Visible
- Winter Visibility
- Cask Location